



Air Quality Management Services, Inc.

“Discovering Solutions for Healthier Living”

December 17th, 2025

Acorn Engineering, Inc.
C/o Peter Heil
PO Box 3372
Portland, Maine 04104



Re: Mold & Asbestos Assessment at 8 River Road property in Bowdoinham, Maine.

AQM Project #: 25-846

Air Quality Management Services, Inc. (AQM) conducted a mold and asbestos assessment at your request on December 2nd, 2025 at the above location, to characterize the presence of mold (airborne and on surfaces) as well as asbestos containing building materials (ACBM) to prepare for renovation or demolition.

I. Background

Assessment requested for facility feasibility (use) study.

II. Testing

Mold Air samples: Air samples were collected using a high-volume sampling pump and Air-O-Cell media (Spore-Trap) cassettes. Samples were collected in representative locations to determine airborne particle and fungal burdens. Samples were collected at 15 liters per minute flow rate for either 5 or 10 minutes. An ambient outdoor sample was collected as a comparative reference. Results for these samples are summarized in Table 1.

Mold Surface samples: Tape lift samples were collected from representative surfaces to evaluate mold growth and/or settled spores / dust. Samples were collected using special microscope slides fitted with clear tape tabs. Results for these samples are summarized in Table 2.

Asbestos Bulk samples: Samples collected from suspected building materials and submitted for analysis by Polarized Light Microscopy (PLM) using EPA 600/R-93/116 and / or section 2.3 (Non-Friable Organically Bound method). Results for these samples are summarized in Table 3.

Samples for mold and asbestos analysis were submitted to EMSL Analytical in Cinnaminson, New Jersey.

III. Observations (see photos for examples and more details)

- AQM observed numerous water stained ceiling tiles. Tenant reported roof leaks with the roof being repaired / replaced. Cannot rule out rodent activity (urine) could be source of some staining.
- In general, the 1st floor was not well kept, very dusty in hard to reach / clean areas. Dust can harbor a wide range of allergens and irritants, including mold spores (from outdoors), potentially causing health issues when disturbed and inhaled.
- Water is pouring into the Basement through foundation wall. Water is pooling in the Basement. Some water is draining into sump and pumped out.
 - Where water is pumped (rear side of Building), water is saturating ground therefore potentially draining back into Basement.
 - Gutters are present on each roof line, however downspouts appear to deposit water along and at foundation, therefore water from these downspouts may leak into Basement.
- AQM observed mold growth on surfaces in the Basement. Such surfaces are contents / items and Ceiling surfaces (i.e. floor joists). Location and pattern of this growth is consistent with surface condensation issues from uncontrolled humidity. Water intrusion may exacerbate humidity and condensation issues especially if water pools and becomes stagnant.
- AQM observed some mold on roof sheathing surfaces. This growth is likely a result of reported roof leaks. Mostly, surfaces in the Attic appeared free of observed mold and weathered.
- AQM observed rodent activity in the 1st floor and Attic. Droppings observed on surfaces. Exposure to rodent antigens may produce allergic reactions in individuals susceptible to such allergens.
- AQM observed suspected building materials for sampling and determination of asbestos fibers. These building materials are flooring, finish ceiling and wall materials.
 - Note: the following was considered during this project (excerpt from MEDEP Chapter 425); “Specific building materials that do not require inspection, sampling, and analysis for asbestos include: wood, fiberglass, glass, plastic, metal, laminates, foam, rubber and gypsum board when joint compound was used only as a filler and not as a layered component, and intact caulking and glazings.”

IV. Results

Airborne Mold Sampling (refer to lab report for full details)

Table 1; (Air sample results are summarized as follows:)

Sample #	Location	Overall Airborne Mold Level (1)	Mold Type(s) of Concern / Amplified Mold (2)
A1	Outdoors (3)	Trace	Not Applicable
A2	1 st floor	Trace	None
A3	Basement	Moderate	Basidiospores, Low/Moderate

(1) All spores from all origins (indoor and outdoor), with levels based on AQM experience

(2) Spores at atypical levels and/or significantly elevated indoors, based on industry consensus and AQM experience. Note that for Aspergillus/Penicillium-like spores, a common outdoor spore that is also commonly involved in air quality issues, the typical outdoor level in Maine through much of the warmer months is 200 to 300 counts per cubic meter of air (though wide variations can occur).

(3) Comparative Reference Sample

Result for air sample (A3) identified elevated levels of Basidiospores mold spores, as compared to the outdoor control (A1). This is likely related to degraded/rotten wood surfaces in the Basement as these types of spores are commonly associated with wood decay especially in the outdoor environment.

Result for air sample (A2) identified levels and types of mold spores similar to the outdoor control sample (A1) therefore not considered elevated based on this comparison.

Surface Mold Sampling (refer to lab report for full details)

Table 2; (Surface sample results are summarized as follows:)

Sample #	Location	Comments	Mold Type(s) Present at Excess Level (1) or Mold Type(s) of Concern (2)
T1	Basement Ceiling	Visible / Suspected Mold	Arthrospores species, High Cladosporium species, High

(1) Based on AQM experience and/or industry consensus; represents mold growth unless stated otherwise

(2) Spore types strongly correlated with water damage and/or air quality concerns, based on scientific literature and/or industry consensus

Result for this surface sample confirmed levels and types of mold growth of concern.

Asbestos Bulk Building Material Sampling (refer to lab report for full details)

The demolition/renovation impact survey was conducted in accordance with OSHA 29 CFR 1926.1101, and Maine Department of Environmental Protection (MEDEP) Chapter 425 Asbestos Management Regulations (April 3, 2011 revision) and was completed to provide Client with information regarding the presence of Asbestos Containing Building Materials (ACBM) within the interior of the structure to prepare for demolition/renovation. Mr. Randy Geoffroy, an asbestos inspector licensed by MEDEP (AI#-0395), performed this survey.

IV. Results (Continued)

This asbestos demolition/renovation impact survey included:

- Visual identification of suspect ACBM on the interior and exterior of the structures
- Collection of bulk samples (in this case 24 Samples) of suspect ACBM from the interior and exterior of the Building in accordance with MEDEP regulations
- Quantification of ACBM identified by laboratory analysis.

As with any scientific study, an asbestos demolition/renovation impact survey is subject to a variety of limitations. Limitations to be considered in the results of this survey include the following:

- Variations in building materials used during construction and subsequent renovations.
 - In this case, AQM found multiple layers of flooring. Tenant was hesitant of AQM drilling (coring) multiply areas of floor to determine extent of such conditions. Therefore, asbestos containing flooring is suspected to be throughout the building; bottom layer of flooring as well as top layer in Bathroom.
- Inaccessible areas (as applicable and as follows); within wall / ceiling cavities, below sub-floors, above solid ceilings and flooded and frozen basement areas.
- Condition of the structures at the time of the survey.
- In this case, AQM was not asked to sample roofing at this time.

The following is a summary of findings and laboratory analytical results of the survey. Twenty-four (24) samples of suspect ACBM were collected from the interior and exterior of the Building:

Office Structure:

- Two layers of flooring (finish VCT and bottom green vinyl flooring)
- Felt floor underlayment (under green vinyl flooring)
- Homasote fibered wall panels
- Ceiling tiles
- Skim coat on Hallway ceiling

According to MEDEP Chapter 425 Asbestos Management Regulations, bulk samples shall be analyzed until a positive result is obtained or all samples have been analyzed. MEDEP defines ACBM as “any material containing asbestos in quantities greater than or equal to one (1) percent (%) by volume as determined by weight, visual evaluation, and/or point count analysis.” Sampled materials identified by laboratory analysis as ACBM (by definition) consisted of materials in bold red in Table 3 (below).

Sample locations are presented in Section “Asbestos Sample Locations”.

IV. Results (Continued)

Table 3; (Suspected Building Materials sample results are summarized as follows:)

Sample #	Location	Material	% Asbestos	Type
B1 – B3	1 st floor	Larger Ceiling Tiles	ND	----
B4 – B6	1 st floor	Smaller Ceiling Tiles	ND	----
B7 – B9	Hallway	Skim Coat on Ceiling	ND	----
B10 – B12	1 st floor (except Bathroom)	12x12 Floor Tiles (top layer)	ND	----
B13 – B15	Bathroom	Floor Tiles (top layer)	2.2%	Chrysotile
B16 – B18	1st floor	Green Flooring (under top layer)	4.6%	Chrysotile
B19 – B21	1st floor	Tar Paper under Flooring	<0.25, 0.26, 0.65%	Chrysotile
B22 – B24	1 st floor	Fibered Wall Panels	ND	----

ND = None Detected

V. Recommendations

Mold Remedial Recommendations

- Enlist the services of a mold remediation contractor that is knowledgeable with IICRC S500 & S520 Standards (See General Information Section of this Report for more details).
- Isolate the Remediation Areas (See Below) from other areas of the Building, using plastic / polyethylene barrier and negative-air pressure. See Definition for Containment parameters.
- Attic:
 - Remove all insulation to affect cleaning; mold growth may shed from surfaces and deposit in insulation. Also, this is recommended to affect cleaning and removal of rodent activity (droppings), using Detail Clean (see Definitions) methods.
 - Remove and replace water damaged floor boards and ceiling tiles to affect cleaning. May need to extend Containment to 1st floor to control release of dusts into the 1st floor during removal of water stained ceiling tiles.
 - Clean / Treat (see Definitions) roof sheathing / rafter and gable end surfaces in areas of mold growth.
- Basement:
 - Remove all insulation (fibrous / foam board) / contents / items / (any items cleaned in-place should be at the approval / discretion of the Remediation Contractor and Owner).
 - Remove all wood wall systems, only if not load-bearing.
 - Remove all attachments on the ceiling (i.e. duct work and fiberboard, if present) to affect cleaning.
 - Remove all attachments on walls (i.e. pegboards / shelving units / plywood panels, if present) to affect cleaning.
 - Remove all workbenches and built-in shelving units (if present) to affect cleaning.
 - Dry, Clean / Treat (see Definitions) all remaining, exposed surfaces.

V. Recommendations (Continued)

- Detail Clean (see Definitions) all surfaces / contents in Each Remediation Area (See Above), because of the observed surface-mold growth, elevated levels of airborne fungi and/or probability of settled spores, and dusty conditions.
 - This level of cleaning should be used for the 1st floor to address dusty conditions and rodent activity (i.e. droppings). Professional level cleaning not warranted but may provide the best results.
- **IMPORTANT (and if applicable):** With any recommendations for material removal (e.g. wall or ceiling systems), expand area of removal if damages and/or mold growth are found to extend beyond the boundaries initially specified (the Remediation Contractor should ensure that areas / surfaces are carefully inspected in order to make any such determination). Note that in general, building systems / materials should always be removed 2-feet beyond the visible extent of mold growth or water damage / staining.
- Replace building materials / Release Remediation area ONLY after a successful post remedial evaluation.
- Note on chemical methods: use of concentrated bleach / hypochlorite solutions (e.g. RMR, MMR, etc.) has become increasing popular for mold remediation, particularly in attics. This method is acceptable as long as the goal is mold removal and not mold killing. There should be no remaining orange / brown / black residues or stains. This generally requires multiple applications with scrubbing / cleaning in between applications, otherwise mold growth is only partially digested and even faint residues will still give positive mold results during post-remediation verification (PRV) testing. Note that this cleaning method is generally ineffective with rough-texture lumber.

Mold Preventative Recommendations (some or all may or may not pertain in this case)

- Ensure to control humidity in the Building. Ensure that the bathroom ceiling exhaust fan(s), dryer exhaust, Kitchen stove exhaust and/or any other appliance exhaust are installed, properly sealed and operated and vent directly outdoors to prevent humidity issues indoors that can lead to structural impact / mold growth in the Attic and/or other indoor locations. Control humidity in the Basement by use of dehumidifier adequate for the space and/or amount of dampness and humidity present (April Aire or equivalent dehumidifier). Maintain Basement humidity at 40% or less (there is no specific level that will work in all homes). Monitor humidity to ensure proper levels.
 - In this case, there is no shower in the Bathroom therefore exhaust fan in Bathroom would be for odor control.
 - In this case, there is no Kitchen therefore exhaust fan in Kitchen does not apply.
 - In this case, there is no Laundry in this Building therefore exhaust fan for Dryer does not apply.
- Maintain foliage around the Building to keep moisture away from the siding / foundation; ensure adequate sunlight exposure to prevent saturated soil.
- Ensure to correct any plumbing issues and/or water intrusion issues to prevent future damages and mold growth.

V. Recommendations (Continued)

- Consult a Professional Engineer or a competent qualified contractor to control groundwater intrusion into the Basement and/or prevent saturated soil surrounding the foundation / slab by: installing exterior foundation perimeter drainage, sloping the ground away from the foundation / slab 5% (6" for every 10'), installing gutters (If gutters are to be installed ensure they are kept free of debris and the downspouts direct water well-away from the foundation), and water proofing the foundation walls or utilizing other like systems. May consider installation of sump (fitted with pump) in the Basement.
 - In this case, the ground around this Building appears very saturated and AQM observed a stream of water leaking in the Basement. It may take considerable effort to control water from entering the Basement, such as excavation and water control systems (weeping drain and foundation water proofing).

Asbestos Abatement Recommendations:

State and federal regulations require that identified ACBM which may be impacted by planned demolition/renovation activity be removed by a licensed asbestos abatement contractor in accordance with applicable state and federal regulations prior to disturbance by such planned activities.

In accordance with 40 CFR 61, *National Emissions Standards for Hazardous Air Pollutants* (NESHAP), and 06-096 MEDEP Chapter 425, Asbestos Management Regulations (effective date: April 3, 2011), a contractor conducting any demolition and/or renovation activity that would disturb regulated ACBM must: (1) notify the U.S. Environmental Protection Agency (USEPA) Administrator and MDEP of such activities; (2) use proper removal procedures; (3) use proper engineering controls to limit emissions of asbestos fibers; and (4) utilize proper waste disposal. If any hidden suspect ACBM (behind walls, in chases, above ceilings, etc.) is uncovered during the demolition or renovation activities, work must be stopped, and the material tested for asbestos content or presumed positive and dealt with accordingly. All ACBM must be disposed of in accordance with all applicable state and federal requirements.


Note: as for sample set (B19 – B21 – in **Bold Blue** in Table 3), these samples identified asbestos fibers, however below the 1% definition. Occupational Safety and Health Administration (OSHA) standard has a definition for both "asbestos" and "asbestos-containing materials." The definition of asbestos does not have a one percent cut off; therefore, asbestos that is present in percentages less than one percent continues to be covered by the OSHA standard. With this being said, AQM strongly suggests following OSHA Regulations for removal of materials with results at and above the detection limit (i.e. <0.25%). OSHA Class II asbestos work; means activities involving the removal of ACM which is not thermal system insulation or surfacing material. This includes, but is not limited to, the removal of asbestos-containing wallboard, floor tile and sheeting, roofing and siding shingles, and construction mastics. Ensure individuals removing these materials are trained in accordance with OSHA Regulations.

VI. Definitions

- **Finished System** includes the underlying wall / ceiling insulations and appropriate vapor barriers.
- **Detail Cleaning** involves HEPA vacuuming and/or damp wiping with a mild detergent (including hard-to-reach areas / inside / underside / behind furniture and other objects). Following cleaning, there should be no visible debris or dust. All mold growth must be removed from surfaces. HEPA air-scrubbing units of appropriate size and airflow should be operated during cleaning to capture airborne debris and mold spores / fragments.
- **Clean / Treat** involves the application of an appropriate cleaning / treatment system. Surfaces should be thoroughly cleaned including damp / wet cleaning and wiping of surfaces; use cleaning / scrubbing method with appropriate abrasiveness based on characteristics of the material surfaces as well as types and extent of mold growth. All mold growth must be removed from surfaces. Application of any coating must be light; encapsulation is unacceptable unless done after post-remediation testing. **There should never be any visible mold, demolition debris, sheetrock dust, paper or insulation fragments, general dust, etc. remaining on surfaces after Clean / Treatment actions.**
- **Containment:** engineering controls used to minimize cross-contamination from affected to unaffected areas by airborne contaminants, foot traffic, or material handling. Containment systems normally consist of 6-mil polyethylene sheeting, often in combination with air pressure differentials (negative-air pressure), to prevent cross-contamination.

AQM appreciates this opportunity to have aided in this project. In the event you have questions or require further assistance, please do not hesitate to contact me.

Sincerely,


Industrial Hygienist
Randy Geoffroy

Council-certified Microbial Remediation Supervisor (CMRS)
Council-certified Microbial Investigator (CMI)
MEDEP Licensed Asbestos Inspector (AI-0395)

GENERAL INFORMATION & REFERENCES

GENERAL INFORMATION & REFERENCES

Special Notes

Negative air machines equipped with HEPA filtration in addition to HEPA filtered vacuums and poly isolation barriers should be used during the renovations to control dust and potential communication of contaminants to areas outside the immediate concern and to focus drying efforts using dehumidification. The lists provided are designed for guidance only based on analytical results and visual observations made the day of the initial evaluation. The Contractor performing the remedial activity should note any additional items not noted in these lists that have mold damage or if significant degradation of other material is discovered during the remedial actions recommended. AQM is not present during renovation activity and cannot be held responsible for all materials discovered during destructive renovations. Discovery of materials not tested or conditions not characterized should be reported to AQM for further evaluation prior to proceeding with the activity leading to their discovery.

Post-Remedial Evaluation

A post remedial evaluation should be conducted prior to releasing the area for reconstruction and re-occupancy. Air and/or surface samples in addition to moisture readings should be collected in areas of known previous impact to determine if remedial actions were effective prior to release. Air samples will be compared to background levels (outdoor control) for release. Air samples collected inside the remediation area should be similar to or less in concentration to those collected outside the area as a control (i.e. outdoor control). Surface samples will be collected on exposed surfaces in the remediation area to confirm that the remedial actions were prudent and that mold growth of concern (i.e. Aspergillus, Penicillium, Chaetomium, Ulocladium, Fusarium, & Stachybotrys) has been removed from surfaces. In the event contamination has not been significantly reduced, re-cleaning should be accomplished. IICRC S520 Standards suggest Condition 2 and 3 areas be returned to Condition 1 before release.

References

Institute of Inspection Cleaning and Restoration Certification Documents should be referenced for the remediation / cleaning activities – implementing most recent editions of Standards

- ❑ IICRC S500 – Standard and Reference Guide for Professional Water Damage Restoration, 2021 Edition.
- ❑ ANSI/IICRC S520 – 4th Edition 2024 Mold Remediation Standard and Reference Guide for Professional Mold Remediation
- ❑ OSHA SHIB 03-10-10 “A Brief Guide to Mold in the Workplace”
- ❑ USEPA – EPA 402-K-01-001 Mold Remediation in Schools and Commercial Buildings
- ❑ New York City – Guidelines on Assessment and Remediation of Fungi in the Indoor Environments
- ❑ National Air Duct Cleaners Association (NADCA) Documents - ACR (2021 Edition) – Assessment, Cleaning and Restoration

An Insured and Certified Professional Remediation Company should be retained to conduct the work as stated above. Competent knowledge of the above standards should be ensured.

ASSESSMENT LIMITATIONS

ASSESSMENT LIMITATIONS

The observations, conclusions and recommendations described in this assessment report were made under the conditions stated herein, taking into account any information / concerns provided or reported to AQM, and were arrived at in accordance with generally accepted standards related to indoor air quality investigations and good industrial hygiene practice. The conclusions presented in the report were based solely upon the services described herein, and not on scientific tasks or procedures beyond the scope of described services, time and/or any budgetary constraints. Assessments were made at the request of the Client based on information's provided at the time of authorization to proceed with the evaluation.

The findings relating to this assessment were not intended to be exhaustive in nature, nor do they attempt to identify all possible source of indoor contaminants such as chemical or mold throughout the entire structure. Building materials may contain asbestos. In the event that asbestos building materials are suspected, further testing should be performed prior to renovations / demolition of affected building materials. Testing of building materials for asbestos will be in accordance with applicable local / state / federal standards. Also, painted surfaces may contain lead. Lead testing should be performed for Buildings constructed before 1979. The Federal Government banned consumer use of lead-based paints in 1978. If lead-based paints are present, ensure to follow local / state / federal standards for applicable removal actions.

Any measured results, analytical data, and/or physical conditions observed are only valid for the period in which this inspection / testing were conducted. Certain assumptions can be made based on information provided to AQM on/or before the time of the assessment coupled with analytical data and observations made at the time of the inspection / testing.

Where such quantitative laboratory analyses have been conducted by an outside / independent laboratory, AQM has relied upon the data provided, and has not conducted an independent evaluation of the reliability of the data. This data has been reviewed and interpretations made as presented in the report.

Historical events or ambient air conditions that may have existed prior to this assessment cannot be correlated in any way with the enclosed data. No warranty, real or implied, is made as to what was or is the exact cause or source that may have adversely affected the indoor air quality prior to the date of this assessment.

The report is based on AQM's professional opinion and on our experience in conjunction with information gathered during the assessment and laboratory data provided. Information and recommendations set forth in this report are intended to characterize current conditions based on the reported concerns and discoveries made at the time of the inspection and testing period. Information is being provided to aid in the development of corrective actions or remediation that may improve overall conditions identified and/or to improve the overall air quality.

PHOTO DOCUMENTATION

Photo Oder – top to bottom left, top to bottom right

Exterior:



General view



General view



General view



Degraded window coverings on foundation



Downspouts appear to deposit water along foundation



Saturated soils on rear of Building

Interior:



General view



Water stained ceiling tiles



General view



Water stained ceiling tiles



General view



General view



General view



General view



General view



Water stained ceiling tiles



Access to Attic in Hallway



Signs of rodent activity



General view



Signs of rodent activity



General view



General view



Water stained ceiling tiles



General view



General view



General view



General view

Attic:



Signs of rodent activity



General view



General view




General view



General view



General view



General view



General view



Signs of rodent activity



Wood is weathered in some areas, with minor signs of mold growth (black streaks)



Signs of water impact round this plumbing vent stack



General view

Basement:



General view



General view



General view



General view



Water pouring in foundation wall



Shelving system is rotten




Example of mold growth on floor joist (green dots)



Example of mold growth on floor joist (green dots)



Example of mold growth on floor joist (green dots)



Mold growth on stored items



There is a sump pump



Pooling water



Example of mold growth on floor joist (green dots)



Degraded shelving unit and wall system




General view




Pooling water and degraded wall system

SAMPLE LOCATION(S)



1 EXISTING FIRST FLOOR PLAN
1/4" = 1'-0"



1 EXISTING BASEMENT PLAN
1/4" = 1'-0"

© 2025 RYAN SENATORE ARCHITECTURE

RIVER HOUSE
BOWDOINHAM
MAINE

RSA
RYAN SENATORE
ARCHITECTURE
500 CONGRESS STREET, SUITE 2
PORTLAND, MAINE 04101
P: 207-747-5159
C: 207-650-6414
senatorearchitecture.com

CONSULTANTS:

REVISIONS
PROGRESS PRINT ONLY
Not for Construction
11-18-25

DATE:

PROJECT No. 2536




DRAWN BY: CRS

CHECKED BY: RJS



SCALE: AS NOTED

SHEET TITLE:
EXISTING FIRST FLOOR PLAN

EX-01



1 EXISTING FIRST FLOOR PLAN
1/4" = 1'-0"



1 EXISTING BASEMENT PLAN
1/4" = 1'-0"

PROGRESS PRINT ONLY
Not for Construction
11-18-25

SUPPORTING DOCUMENTATION

MOLD SAMPLING RESULTS



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Microbiology Chain of Custody

EMSL Order Number (Lab Use Only):

372519678

EMSL Analytical, Inc.
200 Route 130 North

Cinnaminson, NJ 08077
PHONE: 1-800-220-3675
FAX: (856) 786-5974

Company: Air Quality Management Services		EMSL-Bill to: <input checked="" type="checkbox"/> Different <input type="checkbox"/> Same <small>If Bill to is Different note instructions in Comments**</small>	
Street: PO Box 2491		<i>Third Party Billing requires written authorization from third party</i>	
City: Lewiston	State/Province: ME	Zip/Postal Code: 04241	Country: United States
Report To (Name): Randy Geoffroy		Telephone #: 207-657-7360	
Email Address: See Account Notes		Fax #: 207-657-7361	Purchase Order: 25-846
Project Name/Number: 25-846 - Bowdoinham		Please Provide Results: <input type="checkbox"/> FAX <input checked="" type="checkbox"/> E-mail <input type="checkbox"/> Mail	
U.S. State Samples Taken: Maine		Connecticut Samples: <input type="checkbox"/> Commercial <input type="checkbox"/> Residential	

Turnaround Time (TAT) Options* - Please Check

3 Hour 6 Hour 24 Hour 48 Hour 72 Hour 96 Hour 1 Week 2 Week

*Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide. TATs are subject to methodology requirements

Non Culturable Air Samples (Spore Traps) – Test Codes

• M001 Air-O-Cell	• M173 Allegro M2	• M004 Allergenco	• M032 Allergenco-D	• M172 Versa Trap
• M049 BioSIS	• M003 Burkard	• M043 Cyclex	• M002 Cyclex-d	
• M030 Micro 5	• M174 MoldSnap	• M176 Relle Smart	• M130 Via-Cell	

Other Microbiology Test Codes

• M041 Fungal Direct Examination	• M014 Endotoxin Analysis	• M029 Enterococci
• M005 Viable Fungi ID and Count	• M015 Heterotrophic Plate Count	• M019 Fecal Coliform
• M006 Viable Fungi ID and Count (Speciation)	• M180 Real Time Q-PCR-ERMI 36	• M133 MRSA Analysis
• M007 Culturable Fungi	• Panel	• M028 <i>Cryptococcus neoformans</i> Detection
• M008 Culturable Fungi (Speciation)	• M018 Total Coliform (Membrane Filtration)	• M120 <i>Histoplasma capsulatum</i> Detection
• M009 Gram Stain Culturable Bacteria	• M020 Fecal <i>Streptococcus</i> (Membrane Filtration)	• M033-39 Allergen Testing
• M010 Bacterial Count and ID – 3 Most Prominent	• M210-215 <i>Legionella</i> Detection	• M044 Group Allergen (Cat, Dog, Cockroach, Dustmites)
• M011 Bacterial Count and ID – 5 Most Prominent	• M026 Recreational Water Screen	• Other See Analytical Price Guide
• M013 Sewage Contamination in Buildings	• M027 Mycotoxin Analysis	

Preservation Method (Water):

Name of Sampler: Randy Geoffroy

Signature of Sampler:

Sample #	Sample Location	Sample Type	Test Code	Volume/Area	Date/Time Collected
A1	Outdoors	Air	M001	75L	12/2/25
A2	1st Floor	Air	M001	75L	
A3	Basement	Air	M001	75L	
T1	Basement Ceiling	Tap	M041	N/A	

Client Sample # (s): A1, A2, A3, T1

Total # of Samples: 4

Relinquished (Client):

Date: 12/2/25 Time: 1:30

Received (Client):

Date: 12/3/25 Time: 11:20am

Comments:

Email invoices to: connie@aqmservices.com

4 DT



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Tel/Fax: (800) 220-3675 / (856) 786-0262
<http://www.EMSL.com> / cinmicrolab@emsl.com

EMSL Order: 372519678
Customer ID: AIRQ51
Customer PO:
Project ID:

Attention: Randy Geoffroy
Air Quality Management Services, Inc.
PO Box 2491
Lewiston, ME 04241

Phone: (207) 657-7360
Fax: (207) 657-7361
Collected Date: 12/02/2025
Received Date: 12/03/2025 11:20 AM
Analyzed Date: 12/03/2025

Project: 25-846 -Bowdoinham

Test Report: Air-O-Cell™ Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number: Client Sample ID: Volume (L): Sample Location:	372519678-0001 A1 75 Outdoors			372519678-0002 A2 75 1st Floor			372519678-0003 A3 75 Basement		
	Raw Count†	Count/m³	% of Total	Raw Count†	Count/m³	% of Total	Raw Count†	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	1	10*	2.6	-	-	-
Ascospores	-	-	-	-	-	-	3	100	1.8
Aspergillus/Penicillium++	-	-	-	4	200	51.3	4	200	3.6
Basidiospores	5	200	58.8	2	90	23.1	97	4300	78
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium++	-	-	-	-	-	-	-	-	-
Cladosporium	3	100	29.4	-	-	-	6	300	5.4
Curvularia	-	-	-	1	40	10.3	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium++	-	-	-	-	-	-	1	40	0.7
Ganoderma	-	-	-	-	-	-	-	-	-
Myxomycetes++	1	40	11.8	1	10*	2.6	-	-	-
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	1	40	10.3	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Acremonium++	-	-	-	-	-	-	2	90	1.6
Arthrospores	-	-	-	-	-	-	8	400	7.3
Bispora	-	-	-	-	-	-	1	40	0.7
Coelomycetes	-	-	-	-	-	-	1	40	0.7
Total Fungi	9	340	100	10	390	100	123	5510	100
Hyphal Fragment	1	40	-	1	40	-	1	40	-
Insect Fragment	-	-	-	1	40	-	-	-	-
Pollen	1	40	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	44	-	-	44	-	-	44	-
Analyt. Sensitivity 300x	-	13*	-	-	13*	-	-	13*	-
Skin Fragments (1-4)	-	1	-	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	3	-	-	3	-	-	1	-

† Due to method stopping rules, extrapolated raw counts are reported in parenthesis.
++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

Liz Hagenbuch, M.S., Microbiology Manager
or other Approved Signatory

No discernable field blank was submitted with this group of samples.

EMSL Analytical, Inc. maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. EMSL Analytical, Inc. bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. Skin Fragment and Fibrous Particulate ratings are based on the percent of non-fungal material they represent: 1 (1-25%), 2 (26-50%), 3 (51-75%), or 4 (76-100%). Background ratings are based on the total area covered by non-fungal particles: 1 (1-25%), 2 (26-50%), 3 (51-75%), 4 (76-99%), or 5 (100%; overloaded). High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts >= 100 are extrapolated based on the percentage analyzed.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ AIHA LAP, LLC-EMLAP Accredited #100194

Initial report from: 12/08/2025 09:03 AM

For information on the fungi listed in this report, please visit the Resources section at www.emsl.com



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Tel/Fax: (800) 220-3675 / (856) 786-0262
<http://www.EMSL.com> / cinnmicrolab@emsl.com

EMSL Order: 372519678
Customer ID: AIRQ51
Customer PO:
Project ID:

Attention: Randy Geoffroy
Air Quality Management Services, Inc.
PO Box 2491
Lewiston, ME 04241

Phone: (207) 657-7360
Fax: (207) 657-7361
Collected Date: 12/02/2025
Received Date: 12/03/2025
Analyzed Date: 12/03/2025

Project: 25-846 -Bowdoinham

Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Tape Samples (EMSL Method MICRO-SOP-200)

Lab Sample Number:	372519678-0004				
Client Sample ID:	T1				
Sample Location:	Basement Ceiling				
Spore Types	Category				
Alternaria (Ulocladium)	-				
Ascospores	-				
Aspergillus/Penicillium++	-				
Basidiospores	-				
Bipolaris++	-				
Chaetomium++	-				
Cladosporium	*High*				
Curvularia	-				
Epicoccum	-				
Fusarium++	-				
Ganoderma	-				
Myxomycetes++	-				
Pithomyces++	-				
Rust	-				
Scopulariopsis/Microascus	-				
Stachybotrys/Memnoniella	-				
Unidentifiable Spores	-				
Zygomycetes	-				
Arthrospores	*High*				
Hyphal Fragment	-				
Insect Fragment	-				
Pollen	-				
Fibrous Particulate	-				

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

- Denotes Not Detected.

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

* = Sample contains fruiting structures and/or hyphae associated with the spores.

Liz Hagenbuch, M.S., Microbiology Manager
or other Approved Signatory

No discernable field blank was submitted with this group of samples.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ AIHA LAP, LLC-EMLAP Accredited #100194

Initial report from: 12/08/2025 09:03 AM

For information on the fungi listed in this report, please visit the Resources section at www.emsl.com

ASBESTOS BULK SAMPLING RESULTS



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

042523674

EMSL Analytical, Inc.
200 Route 130 North

Cinnaminson, NJ 08077
PHONE: 1-800-220-3675
FAX: (856) 786-5974

Company : Air Quality Management Services		EMSL-Bill to: <input checked="" type="checkbox"/> Different <input type="checkbox"/> Same If Bill to is Different note instructions in Comments**	
Street: PO Box 2491		Third Party Billing requires written authorization from third party	
City: Lewiston	State/Province: ME	Zip/Postal Code: 04241	Country: United States
Report To (Name): Randy Geoffroy		Telephone #: 207-657-7360	
Email Address: See Account Notes		Fax #: 207-657-7361	Purchase Order: 25-846
Project Name/Number: 25-846 - Bowdoinham		Please Provide Results: <input type="checkbox"/> FAX <input checked="" type="checkbox"/> E-mail <input type="checkbox"/> Mail	
U.S. State Samples Taken: Maine		Connecticut Samples: <input type="checkbox"/> Commercial <input type="checkbox"/> Residential	

Turnaround Time (TAT) Options* - Please Check

3 Hour 6 Hour 48 Hour 72 Hour 96 Hour 1 Week 2 Week

*For TEM Air 3 hr through 6 hr, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

PCM - Air <input type="checkbox"/> Check if samples are from NY <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA	TEM - Air <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312	TEM - Dust <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167)
PLM - Bulk (reporting limit) <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input checked="" type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)	TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 TEM - Water: EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	Soil/Rock/Vermiculite <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> TEM Qual. via Filtration Technique <input type="checkbox"/> TEM Qual. via Drop-Mount Technique Other: <input type="checkbox"/>

Check For Positive Stop - Clearly Identify Homogenous Group Filter Pore Size (Air Samples): 0.8µm 0.45µm

Samplers Name: Randy Geoffroy AI0395 Samplers Signature: *[Signature]*

Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
B1-B3	Larger Ceiling Tiles		12/2/05
B4-B6	Smaller Ceiling Tiles		
B7-B9	Sk. in Coat Hall (Ceiling)		
B10-B12	12x12 Floor Tiles		
B13-B15	Bath Floor Tiles		
B16-B18	Green Floor Tiles		
B19-B21	Tar Paper Below Green Tiles		
B22-B24	Wall Panels		

Client Sample # (s): B1 - B24 Total # of Samples: 24

Relinquished (Client): *[Signature]* Date: 12/2/05 Time: 10:30

Received (Lab): *[Signature]* Date: 12/3/05 Time: 11:00

Comments/Special Instructions:

Email invoices to: connie@aqmservices.com

2401



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-5974
<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order ID: 042523674
Customer ID: AIRQ51
Customer PO: 25-846
Project ID:

Attn: Randy Geoffroy
Air Quality Management Services, Inc.
PO Box 2491
Lewiston, ME 04241
Phone: (207) 657-7360
Fax: (207) 657-7361
Collected: 12/ 2/2025
Received: 12/03/2025
Analyzed: 12/09/2025
Proj: 25-846 - Bowdoinham

Summary Test Report for Asbestos Analysis of Bulk Material

Client Sample ID: B1 **Lab Sample ID:** 042523674-0001
Sample Description: Larger Ceiling Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/05/2025	Brown	80.0%	20.0%	None Detected	

Client Sample ID: B2 **Lab Sample ID:** 042523674-0002
Sample Description: Larger Ceiling Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/05/2025	Brown	80.0%	20.0%	None Detected	

Client Sample ID: B3 **Lab Sample ID:** 042523674-0003
Sample Description: Larger Ceiling Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/09/2025	Brown	90.0%	10.0%	None Detected	

Client Sample ID: B4 **Lab Sample ID:** 042523674-0004
Sample Description: Smaller Ceiling Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/05/2025	Gray/White	80.0%	20.0%	None Detected	

Client Sample ID: B5 **Lab Sample ID:** 042523674-0005
Sample Description: Smaller Ceiling Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/05/2025	Gray/White	80.0%	20.0%	None Detected	

Client Sample ID: B6 **Lab Sample ID:** 042523674-0006
Sample Description: Smaller Ceiling Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/09/2025	Gray/White	80.0%	20.0%	None Detected	

Client Sample ID: B7 **Lab Sample ID:** 042523674-0007
Sample Description: Skim Coat Hall Ceiling

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/05/2025	White	0.0%	100.0%	None Detected	



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-5974
<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order ID: 042523674
Customer ID: AIRQ51
Customer PO: 25-846
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Material

Client Sample ID: B8 **Lab Sample ID:** 042523674-0008

Sample Description: Skim Coat Hall Ceiling

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/05/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: B9 **Lab Sample ID:** 042523674-0009

Sample Description: Skim Coat Hall Ceiling

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/09/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: B10 **Lab Sample ID:** 042523674-0010

Sample Description: 12x12 Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025	Tan	0.0%	100%	None Detected	

Client Sample ID: B11 **Lab Sample ID:** 042523674-0011

Sample Description: 12x12 Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025	Tan	0.0%	100%	None Detected	

Client Sample ID: B12 **Lab Sample ID:** 042523674-0012

Sample Description: 12x12 Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/09/2025	Tan	0.0%	100%	None Detected	

Client Sample ID: B13 **Lab Sample ID:** 042523674-0013

Sample Description: Bath Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025	Beige	0.0%	97.8%	2.2% Chrysotile	

Client Sample ID: B14 **Lab Sample ID:** 042523674-0014

Sample Description: Bath Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025					Positive Stop (Not Analyzed)

Client Sample ID: B15 **Lab Sample ID:** 042523674-0015

Sample Description: Bath Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025					Positive Stop (Not Analyzed)



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-5974
<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order ID: 042523674
Customer ID: AIRQ51
Customer PO: 25-846
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Material

Client Sample ID: B16 **Lab Sample ID:** 042523674-0016

Sample Description: Green Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025	Green	0.0%	95.4%	4.6% Chrysotile	

Client Sample ID: B17 **Lab Sample ID:** 042523674-0017

Sample Description: Green Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025				Positive Stop (Not Analyzed)	

Client Sample ID: B18 **Lab Sample ID:** 042523674-0018

Sample Description: Green Floor Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025				Positive Stop (Not Analyzed)	

Client Sample ID: B19 **Lab Sample ID:** 042523674-0019

Sample Description: Tar Paper below Green Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025	Black	0.0%	100%	<0.25% Chrysotile	

Client Sample ID: B20 **Lab Sample ID:** 042523674-0020

Sample Description: Tar Paper below Green Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/05/2025	Black	0.0%	99.7%	0.26% Chrysotile	

Client Sample ID: B21 **Lab Sample ID:** 042523674-0021

Sample Description: Tar Paper below Green Tiles

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	12/09/2025	Black	0.0%	99.3%	0.65% Chrysotile	

Client Sample ID: B22 **Lab Sample ID:** 042523674-0022

Sample Description: Wall Panels

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/05/2025	Brown	90.0%	10.0%	None Detected	

Client Sample ID: B23 **Lab Sample ID:** 042523674-0023

Sample Description: Wall Panels

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/05/2025	Brown	90.0%	10.0%	None Detected	



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-5974
<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order ID: 042523674
Customer ID: AIRQ51
Customer PO: 25-846
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Material

Client Sample ID: B24

Lab Sample ID: 042523674-0024

Sample Description: Wall Panels

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	12/09/2025	Brown	90.0%	10.0%	None Detected	

PLM: Cert# BA-0257(EK) Cert# 0256(BT)

PLM EPA NOB: Cert# BA-0257(EK) Cert# 0256(BT)

Analyst(s):

Brett Teixeira	PLM (4) PLM Grav. Reduction (2)
Emilie Kalbach	PLM (8) PLM Grav. Reduction (6)

Reviewed and approved by:

Samantha Sweeney, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This is a summary report; official reports are available on LabConnect or upon request and relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA LAP, LLC-IHLAP Lab 100194, PA ID# 68-00367, LA #04127

Initial report from: 12/09/2025 12:54:39

CERTIFICATIONS



State of Maine
Department of Environmental Protection

LICENSE

Air Quality Management Services, Inc.

Asbestos Consultant
(Full)

License Number: SF-0075

Expiration Date: 07/31/2026



STATE OF MAINE
DEPARTMENT OF ENVIRONMENTAL PROTECTION



JANET T. MILLS
GOVERNOR

MELANIE LOYZIM
COMMISSIONER

September 30, 2025

Air Quality Management Services, Inc.
PO Box 2491
Lewiston, ME 04241-2491

Dear Licensee:

Asbestos application(s) for individual certification of the **two** employee(s) listed below have been received and **approved**. Individual certification numbers are listed below and wallet card(s) are enclosed. Card(s) are property of the individual to whom each is issued. Your responsibility as a licensee is to ensure delivery of the cards to persons in your employment. This letter should be retained for your company files as record of certification. **Please attach 1 updated passport size photo with every application.**

Remember, in Maine all **certified employees** working on an asbestos abatement project, whether conducting removal/repair, air monitoring, design, inspection, or analysis functions, **must work for a State of Maine licensed asbestos firm** and carry his/her wallet card(s) on the job site.

As a reminder, prior to renewing your asbestos certification, the State of Maine **requires** an annual refresher course to be taken before submitting a renewal application. A certificate shall expire one year from the last day of the month from the date of issuance, **or on the last day of the month that the training certificate expires**, whichever is sooner.

All our asbestos forms can be found at <https://www.maine.gov/dep/waste/asbestos/forms.html>
Thank you for your cooperation and your completed application(s).

<u>Name</u>	<u>Category</u>	<u>Certification #</u>	<u>Exp. Date</u>
Randy D. Geoffroy	Air Monitor	AM-0355	09/30/2026
Randy D. Geoffroy	Inspector	AI-0395	09/30/2026

Sincerely,


Sandra J. Moody, Environmental Specialist
Division of Remediation
Bureau of Remediation and Waste Management

AUGUSTA
17 STATE HOUSE STATION
AUGUSTA, MAINE 04333-0017
(207) 287-7688 FAX: (207) 287-7826

BANGOR
106 HOGAN ROAD, SUITE 6
BANGOR, MAINE 04401
(207) 941-4570 FAX: (207) 941-4584

PORTLAND
312 CAPEN
PORTLAND
(207) 825-5300

website: www.maine.gov/dep



RK



American Council for Accredited Certification

hereby certifies that

Randy D. Geoffroy

has met all the specific standards and qualifications of the re-certification process,
including continued professional development, and is hereby re-certified as a

CMRS

**Council-certified
Microbial Remediation Supervisor**

This certificate expires on October 31, 2026.

Charles F. Wiles, Executive Director

0610026

Certificate Number

This certificate remains the property of the American Council for Accredited Certification.



American Council for Accredited Certification

hereby certifies that

Randy D. Geoffroy

has met all the specific standards and qualifications of the re-certification process,
including continued professional development, and is hereby re-certified as a

CMI

**Council-certified
Microbial Investigator**

This certificate expires on May 31, 2026.

Charles F. Wiles, Executive Director

1605024

Certificate Number

This certificate remains the property of the American Council for Accredited Certification.